


# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-110	Smoke	10/22/2008	ADS/TM	S13GG_057MH	Dry	Yes	1,043.91



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-110	Smoke	10/22/2008	ADS/TM	S13GG_057MH	Dry	Yes	1,043.91

### Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13GG_054G1	S13GG_054MH	S13GG_047MH	129.2448	8
S13EE_003G1	S13EE_003MH	S13EE_007MH	207.664	8
S13GG_041G1	S13GG_041MH	S13GG_047MH	127.2220	8
S13EE_007G1	S13EE_007MH	S13GG_041MH	129.9524	8
S13GG_057G1	S13GG_057MH	S13GG_054MH	244.8514	8
S13EE_046G1	S13EE_046DE	S13GG_041MH	78.66376	8
S13EE_007G2	S13EE_007MH	S13GG_054MH	126.3097	8

### Observations & Photos

No smoke was observed during this test.

